



COUPON ANALYSIS REPORT

For: **Water Solutions Engineering Customer**

Date: 2/4/2011

This corrosion coupon report is for the mild steel and copper coupons removed from both cooling tower coupon racks on 01/06/2011. The mild steel corrosion rates were excellent and well below our limit of 3.0 MPY. The copper corrosion rates were excellent as well and below the target limit of 0.3 MPY. Typically, the industry standard is to allow the coupons to be exposed for approximately 90 days and these were exposed for 86 days. These corrosion rates were very good especially given the fact that there were some problems with the ORP probe giving false readings during the initial exposure to these systems. We are confident that the mild steel and copper corrosion rates will be maintained or improve from this point forward.

These results below provided by an independent laboratory reveals that the chemical program which is in place on both tower systems is performing above expectations and the equipment serviced by these towers are very well protected by the Water Solutions Engineering™ chemical water treatment program.

Thank you for your business and we look forward to continuing to provide your company with excellent water treatment programs and service in the future.

Water Solutions Engineering


PO Box 1037 TCAS, Blountville, TN 37617
P: 423.323.4195, 800.999.4195
f: 423.323.4908

PO Box 30731, Knoxville, TN 37930
P: 865.984.3430, 800.999.4195
f: 865.983.9686


PO Box 2820, Greenville, SC 29602
P: 864.295.9500, 800.358.9981
f: 864.295.1360

PO Box 1839, Skyland, NC 28776-1839
P: 828.251.2420, 800.999.4195
f: 423.323.4908


Specimen No.: 07	Date Installed: 10/12/10
Coupon Type: ½ inch C1010 Mild Steel	Date Removed: 1/6/2011
System ID: K1 Tower	Exposure: 86 Days
Sampling Point: Coupon Rack	Corrosion Rate: 0.10 MPY



Specimen No.: 17	Date Installed: 10/12/2010
Coupon Type: ½ Inch CDA110 Copper	Date Removed: 1/6/2011
System ID: K1 Tower	Exposure: 86 Days
Sampling Point: Coupon Rack	Corrosion Rate: 0.18 MPY



Specimen No.: 06	Date Installed: 10/12/2010
Coupon Type: ½ inch C1010 Mild Steel	Date Removed: 1/6/2011
System ID: K3 Tower	Exposure: 86 Days
Sampling Point: Coupon Rack	Corrosion Rate: 0.13 MPY



Specimen No.: 14	Date Installed: 10/12/2010
Coupon Type: ½ Inch CDA110 Copper	Date Removed: 1/6/2011
System ID: K3 Tower	Exposure: 86 Days
Sampling Point: Coupon Rack	Corrosion Rate: 0.19 MPY

